

## Materials in orthodontics



## Removable appliances

- Acrylic plate
- Metal wire (stainless steel)
  - active for realignment
  - passive for retention
- Screws

### Space maintainer

 assist normal tooth eruption after premature loss, injury or other problem

### Retainer

 prevent relapse of teeth or jaws to their original positions after completion of the therapy



www.imedo.de/practice/provider/show/450271-dr-michael-de-cassan

#### http://www.stratfordorthodontics.ca/Portals/0/partsofbraces.swf



## Fixed appliances

# Bracket Small metal, plastic or ceramic attachment glued to the teeth

# Archwire The main wire track that connects all

the brackets

and guides the direction

the teeth

The rubber bands that connect between different parts of the braces

Elastics


#### Molar Band

The thin ring of metal around the back teeth usually with a hook to attach elastics





www.bracesreview.com



#### Power Chain

Length of elastic bands that joins several teeth to pull them together

#### O Ring

Tiny elastic band (clear or coloured) that holds the archwire into the slot of the bracket



www.archwired.com/Photos-Sherri.htm

www.nelsonortho.co.nz/newbracesguide.htm



## Implant failure

## Causes of implant failure




- Critical situations could not be anticipated in implant tests
- Design not appropriate (material combinations, stress distribution, ....)
- Defects or contaminants introduced during manufacture
- Inappropriate sterilisation method, packaging, shipping, ...
- Inappropriate handling by the surgeon (change of the original shape, drilling of holes, ...)
- Inflammation of the surrounding tissue -> loosening, foreign body reaction, allergy, untimely degradation of biodegradable implants, ...
- Insufficient corrosion resistance, wear resistance, fatigue strength, ...
- ...



## Protrusion of the ceramic head through the PE cup and the acetabular shell in total hip replacement









The polyethylene cup had worn off and was broken. The ceramic head was intact. It was duller and blackened on its superior aspect in comparison to its non-contact surface (A). The head had fully penetrated the acetabular shell (B)

## Mechanical heart valve

 Increased risk of blood clotting (anti-coagulants needed)



http://cape.uwaterloo.ca/che100projects/heart/files/testing.htm

## Cast 316 L femoral stem

Fatigue failure of metal parts



C. D'Antonio in Handbook of case histories in failure analysis, Vol. 2, 1999, pp. 448-450



## Failure of a ceramic acetabular insert

## .

## Failure of a Ceramic Cup Insert





The two biggest fragments are from the upper side of the insert

8 fragments are related to the lower part of the insert; one of these fragments should be the failure initiating one

A multitude of small fragments and shivers that are produced during removal of the insert



## Failure of a Ceramic Cup Insert



Arrangement of the fragments in the original cup shape


Fragment 1

X-ray examination of the patient before removal indicates a failure initiation at a fragment with the dimension  $9 \times 4 \text{ mm}^2$ 

Fragment 2




## Failure of a Ceramic Cup Insert



Fragment 1: Longish wear traces due to the friction head-cup

Shell-like chip<sub>Ausbruch</sub>


Fragment 1: cracks under the surface due to high contact loads between insert and head



613



## Failure of a Ceramic Cup Insert




Biocompatible materials - LV 308.106

614

# Shell-like Chip in a Glass Caused by Contact loading with a Diamond Tip







(B. Lawn, Fracture of brittle solids 1995)


## **Black Disposal**








Platelet arrangement indicates mechanical loading of the surface after fracture




## EDX of the Disposal





The disposal is caused by post-fracture clamping of the fragment between insert and Ti overlay.

The patient noticed "crashing" and "scrunching"



C:\USER\JSTAMPFL\HUE\_HE.spc

Al, O ... Elements of the ceramic

C, O ... Elements from the sputtering for electron conductivity



## Why did the insert fail?

- Material defects in ceramics/glasses
  - Pores
  - Inclusions
- -> No pores or inclusions could be found.
- Microstructure
  - Average grain size: 1.62 μm corresponds to the ISO 6474 (< 4.5 μm)</li>
  - Bulk density: 3.975 g.cm<sup>-3</sup> corresponds to to the ISO 6474 (≥ 3.94 g cm<sup>-3</sup>)
- -> no evidence of inadequate microstructure
- Checking wear resistance and flexural strength on broken fragments is impossible

Probable cause: Wear and related effects given before.



## Lessons learned



- Materials and medical devices in ophthalmology
  - Materials for prosthetic devices (contact lenses, IOL, ...) and corresponding requirements
  - Opportunities and limitations
- Materials and medical devices in dentistry
  - Materials used in dental applications (fillings, impression materials, dentures, implants, ...) and corresponding requirements
  - Opportunities and limitations
- Implant failure
  - Causes of implant failure
  - Failure of a ceramic hip cup insert